

# Gabriel<sup>®</sup>

THE ORIGINAL

**SHOCK ABSORBERS  
FOR TRANSIT & COACH  
BUSES**



**FIND MORE AT GABRIEL.COM**  
part lookup, product info, technical help, training & more!



## Shock Absorber Applications For

# TRANSIT & COACH BUSES

Make	Model	Year	Position	Gabriel Shock	Description	OEM Shock
ABC BUS	Additional O.E.M. Interchanges		Front	85708	Models with O.E.M. Number	6243-13790, 6243-14040
				85732		050134513
			Rear (Drive Axle)	85733		12J-5-10
			Rear (Drive Axle)	85729		12L-5-88
			Rear (Trailing Axle)	85727		12L-5-114
BERKSHIRE COACH	Ultra 24	->2023	Front	G63622	Models with Ford E350 or E450 Chassis	<b>Front:</b> 8C24-18045-DA, 8C2Z-18124-D, ASH-1154, AT-163G <b>Rear:</b> 8C24-18080-DB, 8C2Z-18125-D, ASH-1136, AT-164G
			Rear	G63623		
	Ultra 28	->2023	Front	G63622		
			Rear	G63623		
CHAMPION BUS INC	American Coach	-> 2023	Front	G63622	Models with Ford E350 or E450 Chassis	<b>Front:</b> 8C24-18045-DA, 8C2Z-18124-D, ASH-1154, AT-163G <b>Rear:</b> 8C24-18080-DB, 8C2Z-18125-D, ASH-1136, AT-164G
			Rear	G63623		
	Challenger		Front	G63622		
			Rear	G63623		
	Crusader		Front	G63622		
			Rear	G63623		
	LF Transport		Front	G63622		
			Rear	G63623		
DIAMOND COACH	VIP 2000	-> 2023	Front	G63622	Models with Ford E350 or E450 Chassis	<b>Front:</b> 8C24-18045-DA, 8C2Z-18124-D, ASH-1154, AT-163G <b>Rear:</b> 8C24-18080-DB, 8C2Z-18125-D, ASH-1136, AT-164G
			Rear	G63623		
	VIP 2200		Front	G63622		
			Rear	G63623		
	VIP 2500		Front	G63622		
			Rear	G63623		
	VIP 2800		Front	G63622		
			Rear	G63623		

Make	Model	Year	Position	Gabriel Shock	Description	OEM Shock
EAGLE MOTOR COACH	Additional O.E.M. Interchanges		Front	85304	Buses with Steel Spring Suspension	5532026
				85303	Models with O.E.M. Number	01-0100-905, 680091
				85305		101364, 5394467, 70041
				85308		014-0100-905
			85314	154-0100-514		
			Front / Rear	85307	6-05-5, 01-0100-020	
			Rear	85713	690060	
				85733	12J-5-10	
ELDORADO NATIONAL	Advance	-> 2023	Front	G63622	Models with Ford E350 or E450 Chassis	Front: 8C24-18045-DA, 8C2Z-18124-D, ASH-1154, AT-163G Rear: 8C24-18080-DB, 8C2Z-18125-D, ASH-1136, AT-164G
			Rear	G63623		
	Front		G63622			
			Rear	G63623		
	Aerolite		Front	G63622		
			Rear	G63623		
FEDERAL COACH	Premier	02 - 08	Front	85920	Models with Freightliner M2-106 Chassis	10-12388-000, 10-12390-000
		09 - 23	Front	85959		10-13760-000, 10-13760-000, 471700002991, 471700002991, SDA471700002991, SDA471700002991
		02 - 23	Rear	85724		16-18708-000, 471700002809
	Spirit	-> 2023	Front	G63622	Models with Ford E450 Chassis	ASH-1154
			Rear	G63623		ASH-1136
	FLXIBLE BUS	City Bus - 51 Passenger		Front	85736	Models with O.E.M. Number
Rear				85736	Models with Rubber Torsion Suspension	6-05-1, 6-05-2, 6-05-3, 6-05-4, 6-05-5, 6-05-6, 6-05-7, 6-05-8
Model 870 Flex Bus, Metro		Rear		85704	Models with O.E.M. Number	87-2520-00001, 87-2520-00003, 97-2210-00001, 97-2210-00002, 97-2210-00003, 97-2210-00004, 97-2210-00005, 97-2210-00006, 97-2210-00009, 97-2210-00011
		Front		85700		22012067, 22012114, 3166657, 3192333, 6-367-12, 6-367-14, 6-367-16, 6-367-8, 97-2201-00151, 97-2210-00011
		Front		85733		97-2210-00170
		Front / Rear		85304		6-05-9, 6-05-13, 6-367-3
		Rear		85311		97-9999-02633
		Rear		85704		22024061, 22025067, 22025305, 695125
		Rear		85708		015813, 97-2210-00157, 97-2210-00164
		N/A		85301		680029
				85305		6-367-7

Make	Model	Year	Position	Gabriel Shock	Description	OEM Shock
FLXIBLE BUS	Additional O.E.M. Interchanges		N/A	85307	Models with O.E.M. Number	97-9999-00807
				85700		06-0367-00151, 6-367-17, 97-9999-02514
				85702		06-0367-00156, 97-2210-00156, 97-9999-02515
				85705		97-2210-00160
				85711		6-367-1, 6-367-11, 6-367-6, 6-367-9, 97-9999-02632
				85712		48-1-241, 680155
				85716		97-9999-02636
				85732		97-9999-02635
				85733		97-9999-02634
				85734		6-05-10
85736	48-1-239, 6-367-2					
FLYER INDUSTRIES	Additional O.E.M. Interchanges	91 - 21	Front	85722	Coaches with Low Floor	009863
			Rear	85708		15813
			Front	85700	Models with O.E.M. Number	22012067, 22012114
				85711		015915, 4975552
GLAVAL BUS CO.	All Models	-> 2023	Front	G63622	Models with Ford E350 or E450 Chassis	8C24-18045-DA, 8C2Z-18124-D, ASH-1154, AT-163G
			Rear	G63623		8C24-18080-DB, 8C2Z-18125-D, ASH-1136, AT-164G
	Concorde II - Series	00 - 15	Front	85928	Models with F-650 chassis with 12,000 & 13,200 lb Front Springs	3584118C2, 4C4Z-18124-JB, 4C4Z-18124-RA, AA-617, AT-812
				83175	Models with F-650 chassis with 10,000 lb Front Suspension	3584116C1, 3584116C2, 4C4Z-18124-QA, AA-616, SDA471700002991
		15 - 23	Rear	85181	Models with F-650 chassis with 19.5" or 22.5" Wheels (22,000 lb GVW)	471700011530, ASH-24658, FC44-18045-BB, FC4Z-18124-A, FC4Z-18124-B
		04 - 11		83317	Models with F-650 chassis with 22,000 lb Multi-leaf Rear Springs	4C4Z-18125-B, 501906C92, ASH-24661
15 - 23	85180	Models with F-650 chassis with 13,500, 15,500 & 19,000 lb Multi-leaf Rear Springs	471700011531, ASH-24660, FC44-18080-AB, FC4Z-18125-A			
GREYHOUND BUS	City Cruiser		Front	85303	Models with O.E.M. Number	12TA-01-013
	MC5, MC7, MC8		Front / Rear	85700		3178157
				3166657, 3192333, 690029		
GRUMMAN BUS	Model 870 Flex Bus		Rear	85704	Models with O.E.M. Number	22025067, 22025305, 97-2210-00001, 97-2210-00002, 97-2210-00003, 97-2210-00004, 97-2210-00005
	Additional O.E.M. Interchanges		Front	85700		690029
LGE COACH-WORKS		-> 2023	Front	G63622	Models with Ford E350 or E450 Chassis	8C24-18045-DA, 8C2Z-18124-D, ASH-1154, AT-163G
			Rear	G63623		8C24-18080-DB, 8C2Z-18125-D, ASH-1136, AT-164G

Make	Model	Year	Position	Gabriel Shock	Description	OEM Shock	
MAN BUS	Americana Bus		Front	85708	Models with O.E.M. Numbers	81-43701-6572	
				85722		81-43701-6573	
			Rear	85708		25-1700-106-654, 81-43701-6543	
	Articulating Bus		Front	85708			81-43701-6538
			Trailing Axle				
			Drive Axle	85709			
	Rear		81-43701-6609, 9020M-1042				
	MOHAWK					Front	85700
85732		050134508					
Rear		85704			97-2201-00011, 97-9999-02320		
		85733			680485		
N/A		83207			MM-6886		
		83225			MM-6957		
		85303			01-0100-905		
		85305			6-367-7		
		85308			MM-74029		
		85702			22012082		
85736		1235233					
MOTOR COACH INDUSTRIES		D 4000			01 - 09	Front	85728
	Rear (Drive Axle)		85729	12-05-1177, 12-05-1261, 12-05-1328			
	Rear (Tag Axle)		85339	12-05-1178, 12-05-1194, 12L-5-99, 90-2587			
	D4005	01 - 15	Front	85728	12-05-1176, 12-05-1260, 12-05-1327, 12L-5-97		
			Rear (Drive Axle)	85729	12-05-1177, 12-05-1261, 12-05-1328		
			Rear (Tag Axle)	85339	12-05-1178, 12-05-1194, 12L-5-99, 90-2587		
	D 4500	01 - 09	Front	85728	12-05-1176, 12-05-1260, 12-05-1327, 12L-5-97		
			Rear (Tag Axle)	85727	12-05-1179, 12-05-1262, 12-05-1264, 12-05-1329, 12L-5-114		
			Rear (Drive Axle)	85729	12-05-1177, 12-05-1328, 12L-5-88		
	D 4505	01 - 09	Front	85728	12-05-1176, 12-05-1260, 12-05-1327, 12L-5-97		
			Rear (Tag Axle)	85727	12-05-1179, 12-05-1262, 12-05-1264, 12-05-1329, 12L-5-114		
			Rear (Drive Axle)	85729	12-05-1177, 12-05-1328, 12L-5-88		

Make	Model	Year	Position	Gabriel Shock	Description	OEM Shock	
MOTOR COACH INDUSTRIES	DL3	01 - 09	Front	85728	Models with O.E.M. Numbers	12-05-1176, 12-05-1260, 12-05-1327, 12L-5-96, 12L-5-97	
			Rear (Tag Axle)	85727		01-205219, 12-05-1262, 12-05-1264, 12-05-1329, 12L-5-100, 12L-5-114, T12-1208	
			Rear (Drive Axle)	85729		12-05-1177, 12-05-1328, 12L-5-88, 12L-5-89	
			Rear (Drive Axle)	85733		12J-5-10	
	E 4500	01 - 09	Front	85711		12-05-1150, 12-05-1165	
			Rear (Tag Axle)	85341		12-05-1139, 12-05-1147, 12-05-1166	
			Rear (Drive Axle)	85970		12-05-1022, 12-05-1102, 12-05-1138, 12-05-1148, 12-05-1188	
	G 4500	01 - 03	Front	85711		12-05-6000, 12-05-6053, 1497835	
			Rear (Tag Axle)	85339		12-05-6002, 12-05-6033, 12-05-6055, 1498565	
			Rear (Drive Axle)	85740		12-05-6001, 12-05-6054	
	J4500	04 - 08	Front	85711		12-05-1150, 12-05-1165, 12-05-1228	
			Front	85340		12-05-1137, 12-05-1142, 12-05-1146	
			Rear (Drive Axle)	85970		12-05-1022, 12-05-1148	
		01 - 19	Front	85711		12-05-1150, 12-05-1165, 12-05-1228	
			Rear (Tag Axle)	85341		12-05-1139, 12-05-1147, 12-05-1166	
			Rear (Drive Axle)	85970		12-05-1022, 12-05-1138, 12-05-1148, 12-05-1188	
	MC5, MC7, MC8		Front	85700		3178157, 680323	
	RTS Bus		Rear	85713		Models with "V" Drive Rear	G1101590GS, G1101590, 680470
	Additional Applications		Front	85700		12-5-1-G, 12-5-1-GS, 12B-5-1-G, 12B-5-1-GS, 12G-5-1, 12J-5-9, 12L-5-69, 12L-5-70, 22012067, 680323, 690029, 97-2201-00151, 97-9999-02514, G5008069, T14-1045GS	
				85711		680544, OE10881	
				85723		97-9999-02585	
85303				12T-1-13, 12TA-01-013, 63-0127GS			
85728				12-05-1242, 12L-5-58, 680374, 680462, 680677, T14-1080			
85704				680322, 695125, 22024061			
Rear			85727	12-05-1244, 680681, 680482			
			85729	12-05-1199, 12-05-1243, 12L-5-89, 680441, 680680			
			85733	12J-5-10GS, 680232, 680485, 12J-5-71, 97-9999-02634			
			85740	1498200, OE10882			
			85702	22045526, 22052014, G1011822, G1201339, OE10086S			
			85708	6314933, 680333, 680369, 97-2210-00164			

Make	Model	Year	Position	Gabriel Shock	Description	OEM Shock
MOTOR COACH INDUSTRIES	Additional Applications		Rear	85312	Models with O.E.M. Number	12J-5-2, 12J-5-4, 12J-5-7
				85339		12L-5-99
				85727		12-05-6068, T14-1082
NEOPLAN BUS	Mini-Bus		Front	85009	Models with O.E.M. Number	24-1700-999-362, BN1002002
			Rear	83216		24-1700-106-149, BT1002011
	Front		85705	25-1700-101-426, CI 1002003		
			Model 40	Additional O.E.M. Interchanges		DZ1002002, CL1002003
			Model 80B			680307, AA1002002, AA1002003, AA1802002, AC1002002, AC1002002GS, AC1002003, DT1802002, GJ1002003, MM1002002, MM1002003
Additional O.E.M. Interchanges						
NEW FLYER	Transit Buses (Low Profile)	91 - 21	Front	85722	Models with O.E.M. Number	009863, 016415, 680346
		02 - 21	Rear	85708		152959, 680671
	Additional O.E.M. Interchanges		N/A	85711		015915, 064845, 680352, 690102
NABI	IKAUS		Front / Rear	85708	Models with O.E.M. Number	4160003214700, 481700124382
NOVA BUS	Additional O.E.M. Interchanges		Front	85377	Low Floor Bus Models with O.E.M. Number	481700131250, 680480, 695393, N16248, N31831
				85700	Models with O.E.M. Number	680323, 680326, 97-2201-00151, 97-9999-02514, G5008070, N22212
			Rear	85702	RTS Bus	22045526, 22052014, G1011822, G1203223, OE 10086S
				85713	RTS Bus with "V" Drive	G1101590
				85733	Models with O.E.M. Number	680470
						12J-5-10
ORION BUS INDUSTRIES	Orion 1		Rear	85308	Models with O.E.M. Number	010234503-4
	Orion 102		Front	85716		050134501-4
			Rear	85716		050230501, 050231505, 680504
	Orion II		Front	85720		0201175034, 020117503-4, 020117504, 20117501, 20117504, 20117505
			Rear	85000		020273541-4
			Rear	85308		010234503-4
	Orion V		Front	85732		0101345084, 010134508-4, 0501345024, 0501345064, 050134506-4, 050134509, 050134510, 050134511, 050134513
			Rear	85716		050231505
	Orion VI		Front	87016		060131507, 060131508
	Orion VII		Front	87016		070131502, 70131506
			Rear	85729		070231514, 070231527, 6430645
	Additional O.E.M. Interchanges		Front	85732		050134508, 680506

Make	Model	Year	Position	Gabriel Shock	Description	OEM Shock	
ORION BUS INDUSTRIES	Additional O.E.M. Interchanges			85307	Models with O.E.M. Number	010134501-4	
				85700		OB3166657	
			N/A	85711		680352, 690102, OB020570	
				85716		0502315014, 050231501-4, 0502315024, 050231502-4, 050231507, 97999902636, 97-9999-02636, OB020764	
				85732		0501345-11, 97-9999-02635	
			Rear	85712		A-4890	
PREVOST	H3 Bus, H3 VIP Bus	96 - 09	Front	85329	Models with O.E.M. Number	630134, 680422, 481700999376	
			Rear	85736		481700999386, 630127, 650407	
	XL II Bus, XL II MTH Bus	99 - 06	Front	85329		481700999376, 630134, 680422	
			Rear	85713		630253	
		99 - 03	Rear	85736		650407	
	XL-45 Coach	89 - 00	Front	85329		630134, 680422, 481700999376	
			Rear	85736		481700999386, 630127, 650407	
	Additional O.E.M. Interchanges			Front		85303	12T-1-13
				Front		85329	481700000207, 630103, 630234, 630236, 63-1013
				Front		85700	G5008070
				Front		85728	19501289
				Rear		85339	19501669, 19506846
				Rear		85702	G1011822
				Rear		85713	481700000209, 630001, 630080, 680492, 690060
				Rear		85729	19501288, 12L-5-89
				Rear		85736	630161
		Rear	85740	19501547			
STARCRAFT BUS CO.	All Models	> 2023	Front	G63622	Models with Ford E350 & E450 Chassis	8C24-18045-DA, 8C2Z-18124-D, ASH-1154, AT-163G	
			Rear	G63623		8C24-18080-DB, 8C2Z-18125-D, ASH-1136, AT-164G	
	Allstar XL & XLT - Series	00 - 15	Front	83175	Models with F-650 chassis with 10,000 lb Front Suspension	3584116C1, 3584116C2, 4C4Z-18124-QA, AA-616, SDA471700002991	
			Front	85928	Models with F-650 chassis with 12,000 & 13,200 lb Front Springs	3584118C2, 4C4Z-18124-JB, 4C4Z-18124-RA, AA-617, AT-812	
		15 - 23	Front	85181	Models with F-650 chassis with 19.5" or 22.5" Wheels (22,000 lb GVW)	471700011530, ASH-24658, FC44-18045-BB, FC4Z-18124-A, FC4Z-18124-B	
			Rear	85180	Models with F-650 chassis with 13,500, 15,500 & 19,000 lb Multi-leaf Rear Springs	471700011531, ASH-24660, FC44-18080-AB, FC4Z-18125-A	
04 - 11	Rear	83317	Models with F-650 chassis with 22,000 lb Multi-leaf Rear Springs	4C4Z-18125-B, 501906C92, ASH-24661			
WHEELED COACH IND	Citimedic models		Front	G63622	Models with Ford E350 & E450 Chassis	8C24-18045-DA, 8C2Z-18124-D, ASH-1154, AT-163G	
			Rear	G63623		8C24-18080-DB, 8C2Z-18125-D, ASH-1136, AT-164G	



# QUESTIONS ANSWERED.

800.999.3903 | ANSWERGARAGE.COM



# ANSWER GARAGE®



# Gabriel®

THE ORIGINAL

**Ride Control Answer Garage/Tech Line:**

**800.999.3903**

For application, technical and  
product questions  
Monday - Friday, 8AM - 5PM CT

**Gabriel Customer Service:**

**800.251.5932**

To place and track orders  
Monday - Friday, 7AM - 5PM CT

## Watch our Videos:

**Good Shocks vs.  
Bad Shocks**



**Gabriel®  
Shock Selector**



**LTV™ Severe  
Duty Shocks**



**FIND MORE AT GABRIEL.COM**  
part lookup, product info, technical help & training

